Steps in the 3 dimensional laser scan process to final installation


Requirement: maintenance staff needs access to top of mill bearing housing without erecting scaffolding. Access from walkway level above housing.








1. Laser scan on site, producing 3 dimensional point clouds




3. Final solids models





5. Design of platforms around scanned model in SolidWorks



6. Produce fabrication and installation drawings of platforms

